RECEIVING INSPECTION REPORT

2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM Plant #10

DATE REC'D. 5-13-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.
322	0	104	0	23			

O R ACCT. OR W.O. NO.

S.O. NO.

CHARGE TO

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
14	738080 Solenoid Clip ES 010680	14	—	New Store

RECEIVED BY Barcelos

INSPECTED BY

DATE 5-17-57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1089

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 12164

RECEIVED FROM Plant #9

DATE REC'D. 5-13-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.
322	000000	119	0	23	5	05	

O R ACCT. OR W.O. NO.

S.O. NO.

CHARGE TO

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
20	738142NC Worm Gear Modified DS #7662	20	—	Hold Area

RECEIVED BY Barcelos

INSPECTED BY

DATE 5-14-57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1089